

08-02-411P

Date: 2/22/2008 01:19 PM
Estimate ID: CH08-02-023
Estimate Version: 0
Committed
Profile ID: CUSTOMIZED

Bryant Damage Appraisers, Inc

PO Box 5103, Chesapeake, VA 23324
(757) 494-1240
Fax: (757) 545-3377

bda.bda@verizon.net
(800) 633-4963

Damage Assessed By: R.L. Bryant

Insurance Co: Scott Macleay w/ CAPSTONE ISG
(757) 420-9555

Condition Code: Average
Date of Loss: 2/17/2008
Deductible: UNKNOWN
Assignment # CH08-02-023
Policy No: 1-4131

Type of Loss: Collision

Insured: HRT Hampton Roads Transit Bus # 1906
Address: 18th Street, Norfolk, VA
Telephone: Work Phone: (757) 420-9555

Mitchell Service: 911000

Description: 04 Gillig City Passenger Bus
VIN: 15GGD291641074431
Mileage: 115,195
OEM/ALT: O
Color: White

License: 114-838L VA

Search Code: B678924

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>MANUAL ENTRIES</u>							
1	900500	BDY *	REMOVE/REPLACE	FRT BUMPER BICYCLE RACK DL2	100536	232.40 *	2.5*
2	900500	BDY *	REPAIR	FRT BUMPER CENTER	Existing		2.0*
3	900500	BDY *	REPAIR	FRT BUMPER END CAP L	Existing		1.5*
4	900500	REF *	REFINISH/REPAIR	FRT BUMPER ASSEMBLY	Existing		2.5*
5	900500	BDY *	OVERHAUL	FRT BUMPER ASSEMBLY	Existing		4.0*
6	900500	BDY *	REPAIR	FRT ENTRANCE DOOR ASSEMBLY	Existing		2.0*
7	900500	GLS *	REMOVE/REPLACE	FRT ENTRANCE DOOR LWR GLASS	20-40212-000	101.01 *	2.0*
8	900500	BDY *	REMOVE/REPLACE	FRT ENT DOOR RUBBER SEAL FRT	20-44022L085.50	74.53 *	1.0*
9	900500	BDY *	REMOVE/REPLACE	FRT ENT DOOR RUBBER SEAL REAR	20-44022L085.50	74.53 *	1.0*
10	900500	BDY *	REMOVE/REPLACE	R FRT WHEEL OPENING FLAIR	50-35475-001	205.22 *	1.5*
11	900500	BDY *	REMOVE/REPLACE	R REAR WHEEL OPENING FLAIR	50-35475-002	205.22 *	1.5*
12	900500	BDY *	REPAIR	R FRT WHEEL OPENING SKIRT	Existing		1.0*
13		REF	REFINISH/REPAIR	R FRT WHEEL OPENING SKIRT			1.5*
14	900500	BDY *	REMOVE/REPLACE	R FRT CENTER SIDE SKIRT #1	20-45484M003	535.53 *	2.0*
15	900500	BDY *	REMOVE/REPLACE	R FRT CENTER SIDE SKIRT #2	20-47699M000	434.73 *	2.0*
16	900500	BDY *	REMOVE/REPLACE	R MIDDLE SIDE SKIRT	20-49017M000	281.72 *	2.0*
17	900500	BDY *	REMOVE/REPLACE	R SIDE SIGN FRAME 30"X144"	50-15909-005	341.67 *	1.0*
18	900500	BDY *	REMOVE/REPLACE	REAR ENTRY DOOR FRT RUBBER SEAL	20-44022L085.50	74.50 *	1.0*
19	900500	BDY *	REMOVE/REPLACE	REAR ENTRY DOOR REAR RUBBER SEAL	20-44022L085.50	74.50 *	1.0*
20	900500	BDY *	REMOVE/REPLACE	R SIDE AMBER REFLECTOR	51-34803-002	32.00 *	0.2*
21	900500	BDY *	REMOVE/REPLACE	R CURB SIDE LAMPS (2) 110.00	51-4511-000	220.00 *	1.0*

ESTIMATE RECALL NUMBER: 2/22/2008 13:17:53 CH08-02-023

Mitchell Data Version: OEM: JAN_08_A

UltraMate is a Trademark of Mitchell International
Copyright (C) 1994 - 2008 Mitchell International
All Rights Reserved

UltraMate Version: 6.5.014

22	900500	BDY *	REPAIR	REAR ENTRANCE DOOR FRT	Existing	1.0*
23		REF	REFINISH/REPAIR	REAR ENTRANCE DOOR FRT		1.0*
24	900500	BDY *	REPAIR	REAR ENTRANCE DOOR REAR	Existing	1.0*
25		REF	REFINISH/REPAIR	REAR ENTRANCE DOOR REAR		1.0*
26	900500	BDY *	ALIGN	REAR ENTRANCE DOORS ASSEMBLY	Existing	2.0*
27	900500	BDY *	REPAIR	R REAR WHEEL OPENING SKIRT	Existing	2.5*
28		REF	REFINISH/REPAIR	R REAR WHEEL OPENING SKIRT		1.5*
29	900500	MCH *	ADD'L LABOR OP	SAFECY CHECK REAR ENTRANCE RAMP	Existing	1.0*
30	900500	MCH *	ALIGN	SUSPENSION	Existing	4.0*
<u>BODY COMPONENTS</u>						
31	931015	MCH *	ADD'L LABOR OP	SAFETY CHECK	Existing	1.0*
32				Includes Road Test.		
<u>ADDITIONAL COSTS & MATERIALS</u>						
33	936014		ADD'L COST	FLEX ADDITIVE		10.00 *
<u>ADDITIONAL OPERATIONS</u>						
34	933006	FRM	ADD'L OPR	FRAME/RACK SET UP		2.0*
35	933035	FRM	ADD'L OPR	UNIBODY PULL		2.0*
36	933036	FRM	ADD'L OPR	SHEETMETAL PULL		1.5*
37		REF	ADD'L OPR	TWO TONE		
38	933018	REF	ADD'L OPR	MASK FOR OVERSPRAY		10.00 *
39	933020	REF	ADD'L OPR	PAINTED STRIPE		3.0*
40	933021	REF	ADD'L OPR	DE-NIB AND FINESSE		1.5*
<u>ADDITIONAL COSTS & MATERIALS</u>						
41			ADD'L COST	PAINT/MATERIALS		400.00 *
42			ADD'L COST	HAZARDOUS WASTE DISPOSAL		5.00 *

* - Judgment Item

Remarks

All Parts Pricing Provided by Gillig Bus Manufacture (877)264-3800

Prior Damage:

Front-End Panel Right Side cracked

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	34.7	85.00	0.00	0.00	2,949.50	Taxable Parts	2,887.56
Refinish	12.0	85.00	10.00	0.00	1,030.00	Parts Adjustments	721.89
Glass	2.0	85.00	0.00	0.00	170.00	Sales Tax @ 5.000%	180.47
Frame	5.5	85.00	0.00	0.00	467.50		
Mechanical	6.0	85.00	0.00	0.00	510.00	Total Replacement Parts Amount	3,789.92
					Non-Taxable Labor		5,127.00
Labor Summary	60.2				5,127.00		

Date: 2/22/2008 01:19 PM
 Estimate ID: CH08-02-023
 Estimate Version: 0
 Committed
 Profile ID: CUSTOMIZED

III. Additional Costs	Amount	IV. Adjustments	Amount
Taxable Costs	400.00	Customer Responsibility	0.00
Sales Tax @ 5.000%	20.00		
Non-Taxable Costs	15.00		
Total Additional Costs	435.00		
		I. Total Labor:	5,127.00
		II. Total Replacement Parts:	3,789.92
		III. Total Additional Costs:	435.00
		Gross Total:	9,351.92
		IV. Total Adjustments:	0.00
		Net Total:	9,351.92

Point(s) of Impact

2 Right Front Side (P), 3 Right Side (S), 4 Right Rear Side (S)

Inspection Site: Hampton Roads Transet
 Address: City Garage lot
 Hampton, VA
 Inspection Date: 2/18/2008

Repairer: Body Shop Of Owners Choice
 Address: ASE/I-CAR Certified Body Shops

*****V
 Vehicle must be torn down and inspected for hidden damage before any parts are ordered or repairs are started. Written authorization must be given by BDA or Adjuster before any adjustment take place. When supplements are needed shop must be able to provide copies of all original invoices for ALL PARTS INSTALLED on vehicle. If shop is unable to prived this service our office must be contacted before any tear downs take place.

*****T
 THIS IS NOT AN AUTHORIZATION FOR REPAIRS OR GUARANTEE OF PAYMENT !!
 All repairs and\or part replacements listed above to be made instrict accordance with manufacturer's specifications.
 "All Appraisals are subject to review by your Insurance Company to assure accuracy, cost effectiveness, and that accepted industry repair standards are met. You will be contacted within one business day from the receipt of this appraisal if any questions arise."

 ALL SUPPLEMENTS MUST BE INSPECTED BY APPRAISERS AND PHOTOS TAKEN !!

 This estimate has been prepared based on the use of automobile parts not made by the original manufacturer. Parts used in the repair of your vehicle by other than the original manufacturer are required to be at least equal in like kind and quality in terms of fit, quality

ESTIMATE RECALL NUMBER: 2/22/2008 13:17:53 CH08-02-023

Mitchell Data Version: OEM: JAN_08_A

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2008 Mitchell International
 All Rights Reserved

UltraMate Version: 6.5.014

Date: 2/22/2008 01:19 PM
Estimate ID: CH08-02-023
Estimate Version: 0
Committed
Profile ID: CUSTOMIZED

and performance to the original manufacturer parts they are replacing. Warranties applicable to these aftermarket crash and/or other parts are provided by the parts manufacturer or distributor rather than your own motor vehicle manufacturer.

Failure to deliver a copy of this appraisal to the repair shop by the vehicle owner may result in out of pocket expense to the vehicle owner.