


# HRT SUPERVISOR'S REPORT OF OCCURRENCE

PLEASE "PRINT" ALL INFORMATION

Date of Occurrence: 2/17/08 Time: 4:40 am/pm Day of Week Sun Garage: N CAMERA: Y N  
 Operator: R. BENJAMIN Payroll number: 2589 VEHICLE #: 1906 Division: north  
 Employee Status: Part Time  Full Time  Date of Birth: \_\_\_\_\_ Date of Hire: \_\_\_\_\_  
 Line Name & Number: Route 106 DUTY On Detour: Y  N  
 Traffic Control: Stop Sign  Traffic Light  Yield  None   
 Weather Condition: (Circle One) Clear Cloudy  Fog  Rain  Snow  Ice  Streets: Wet  Dry Icy   
 Speed, just before impact: HRT 7mph Other Vehicle (s) 10mph Did you blow the horn Y  N  
 Speeds, when vehicle/person first seen: HRT 6 Other Vehicle (s) 10mph  
 Distance first seen: \_\_\_\_\_ (ft) Distance traveled after impact: HRT 25 (ft) Other Vehicle (s) 50  
 Daylight  Dark with street lights  Dark without street lights   
 Direction of: HRT West Other Vehicle (s) South  
 Location on: 216th Street Nearest Cross Street: Huntington City: ANN  
 Type of occurrence: Collision w/vehicle  Hit fixed object  Other   
 Passenger injury: Onboard  Boarding  Exiting   
 Roadway: Curved  Straight  Under Construction   
 Intersections: Before  Within  Far side  Was view obstructed: Y  N How?  
 Turning movements: Ours: Right  Left  Straight  Backing  Them: Right  Left  Straight  Backing   
 Number of Passengers: HRT 4 Other Vehicle (s) 1  
 (MUST TURN IN ALL COURTESY CARDS WITH THIS REPORT) Number of cards turned in: \_\_\_\_\_  
 Police  N Name PENNINGTON  
 Police action taken: HRT NO Other (s) Ticket

(PUT AN 'X' AT THE POINT OF CONTACT)






DESCRIBE DAMAGE TO VEHICLES:  
 HRT: dent, scratches broken lights ESTIMATED COST \$500.00  
 OTHER VEHICLE: front fender, bumper, grill, lights ESTIMATED COST \$750.00

SUPERVISOR'S OBSERVATION:  
Bus 1906 proceed thru the light when it turned green when he was struck by another vehicle  
John C. [Signature]

WITNESSES: NAME, PHONE # AND ADDRESS: \_\_\_\_\_ (ATTACH ALL STATEMENTS TO REPORT)

(PUT AN 'X' AT THE POINT OF CONTACT)



DESCRIBE DAMAGE TO VEHICLES:

HRT: dent, scratches broken lights

ESTIMATED COST \$500.00

OTHER VEHICLE: front fender, bumper, grill, lights

ESTIMATED COST \$7500.00

SUPERVISOR'S OBSERVATION:

Bus 1906 proceed thru the light when it turned green when he was struck by another vehicle

John King

WITNESSES: NAME, PHONE # AND ADDRESS:

(ATTACH ALL STATEMENTS TO REPORT)

YOU MUST REPORT TO THE LEGAL/RISK DEPARTMENT THE NEXT BUSINESS DAY TO DO REPORT! OPERATOR SIGNATURE: \_\_\_\_\_ PR # \_\_\_\_\_

Supervisor's signature: \_\_\_\_\_

(John King)

PR # 137